

Winter Service Program

2009-2010



TORO Line Painter 1200

Maintenance & Service Performed

- Change Engine Oil
- Replace Engine Oil Filter
- Replace Air Filter and Pre Cleaner
- Clean and Service Fuel Filter
- Replace Spark Plug
- Grease and Lube Machine
- Service Wheels
- Clean Paint Filter Screen
- Check and Adjust Pump Drive Belt
- Inspect Check Valve Diaphragm
- Adjust Paint Control Cable
- Replace Paint Nozzle
- Adjust Pressure Regulator
- Adjust Spray Pump Relief Valve
- Check and Adjust Traction Drive Belt
- Adjust Traction Drive Cable
- Adjust Brake Cable
- Adjust Front Caster Fork (Tracking)
- Adjust Caster Release Cable
- Adjust Gear Shift Linkage
- Check Transmission for Proper Operation
- Test System Operation
- Prepare System for Seasonal Storage

\$179.95



**Keep it 100% Toro
TOUGH.**

Call Today to Book Your Service

Other Service Programs Available:

Syracuse-Buffalo 1-800-564-5297

Albany-VT 1-800-564-5587

www.Grasslandcorp.com



No Pay Till May 10, 2010 or 5% Cash Discount
Free Pick-Up and Delivery on orders over \$1,500

